



NOTES:

1. DO NOT attempt to power more than 3 devices, be it sensors or slave packs, from a single power pack.

1 circuit with RP option wiring

Hubbell Building Automation, Inc.