



DO NOT attempt to power more than 3 devices, be it sensors or slave packs, from a single power pack.

Hubbell Building Automation
 Low Voltage Sensors(devices)
 Requires 33mA each

1 circuit with A/B switching



Building Automation, Inc.