



NOTE:

1. DO NOT attempt to power more than 4 devices, be it sensors or slave packs, from a single power pack.

1 circuit with A/B switching



Hubbell Building Automation, Inc.