



Hubbell Building Automation  
Low Voltage Sensors (devices)  
**Require 33mA each**

MP Power Pack  
Supplies 100mA each

NOTES:

1. Lighting loads A and B turn on when at least one sensor detects motion.
2. DO NOT attempt to power more than 3 devices, be it sensors or slave packs, from a single power pack.
3. No more than 3 power packs should be connected in this way .

**2 circuits w/ 3 Sensors & MP Power Packs**



**Building Automation, Inc.**