



NOTE:

1. DO NOT attempt to power more than 4 devices, be it sensors or slave packs, from a single power pack.

2 circuits with 1 or 2 sensors



Building Automation, Inc.